ISO 20181:2023-02 (E)

Stationary source emissions - Quality assurance of automated measuring systems

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Symbols and abbreviated terms 6
4.1 Symbols 6
4.2 Abbreviated terms 7

5 Principle 7
5.1 General 7
5.2 Limitations 9
5.3 Measurement site and installation 9
5.4 Testing laboratories performing SRM measurements 10

6 Calibration and validation of the AMS (QAL2) 10
6.1 General 10
6.2 Functional test 11
6.3 Parallel measurements with the SRM 12
6.4 Data evaluation 14
6.4.1 Preparation of data 14
6.4.2 Selection of data points from automated SRM 15
6.4.3 Establishing the calibration function 15
6.5 Calibration function of the AMS and its validity 16
6.6 Calculation of variability 18
6.7 Test of variability 19
6.8 QAL2 report 19

7 Ongoing quality assurance during operation (QAL3) 20
7.1 General 20
7.2 Procedures to maintain ongoing quality 21
7.3 Choosing control charts 21
7.4 Control chart limits 22
7.4.1 General 22
7.4.2 Calculation of control chart limits using performance data 22
7.4.3 Calculation of control chart limits using the maximum permissible uncertainty 23
7.5 Zero and span measurements 23
7.5.1 General 23
7.5.2 Frequency of zero and span measurements 23
7.5.3 Extractive gas analysis systems 24
7.5.4 In-situ gas-monitoring AMS 24
7.5.5 Particulate-monitoring AMS 25
7.6 Documentation of control charts 25

8 Annual surveillance test (AST) 25
8.1 General 25
8.2 Functional test 26

8.3 Parallel measurements with the SRM 26
8.4 Data evaluation 27
8.5 Calculation of variability 28
8.6 Test of variability and validity of the calibration function 28
8.7 AST report 29

9 Documentation 29

Annex A (normative) QAL2 and AST functional test of AMS 30

Annex B (normative) Test of linearity 34

Annex C (informative) Control charts 36

Annex D (normative) Documentation 46

Annex E (informative) Examples of calculation of the calibration function and of the variability test 48

Annex F (informative) Example of calculation of the standard deviation sAMS of the AMS at zero and span level 63

Annex G (informative) Example of using the calibration function and testing the variability and validity of the calibration function in the AST 66

Annex H (informative) Implementation of QAL1 70

Annex I (normative) kv and t0,95; N-1 values 71

Annex J (informative)Significanttechnicalchanges 72

Bibliography 74