DIN EN 14625:2025-12 (E)

Ambient air - Standard method for the measurement of the concentration of ozone by ultraviolet photometry

Contents

Page

European foreword 8

1 Scope 9

2 Normative references 10

3 Terms and definitions 10

4 Abbreviated terms 16

5 Principle 16
5.1 General 16
5.2 Measuring principle 16
5.3 Type testing 17
5.4 Field operation and quality control 18

6 Sampling 18
6.1 General 18
6.2 Sampling location 19
6.3 Sampling system 19
6.3.1 Construction 19
6.3.2 Particle filter 19
6.4 Loss of ozone 20
6.5 Control and regulation of sample flow rate 20
6.6 Sampling pump for the manifold 20

7 Analyser equipment 20
7.1 General 20
7.2 Ultraviolet absorption cell 21
7.3 Ultraviolet source lamp 21
7.4 UV detector 21
7.5 Ozone-specific scrubber 21
7.6 Switching valve 21
7.7 Temperature indicator 22
7.8 Pressure indicator 22
7.9 Flow rate indicator 22
7.10 Sampling pump for the analyser 22
7.11 Internal ozone span source 22
7.12 Particle filter 22

8 Type testing of ultraviolet photometric ozone analysers 22
8.1 General 22
8.2 Relevant performance characteristics and performance criteria 23
8.3 Design change 27
8.4 Procedures for determination of the performance characteristics during the laboratory test 27
8.4.1 General 27
8.4.2 Test conditions 27
8.4.3 Response time 29
8.4.4 Short-term drift 31
8.4.5 Repeatability standard deviation 32

8.4.6 Lack of fit of linearity of the calibration function 32
8.4.7 Sensitivity coefficient to sample gas pressure 33
8.4.8 Sensitivity coefficient to sample gas temperature 34
8.4.9 Sensitivity coefficient to the surrounding temperature 34
8.4.10 Sensitivity coefficient to electrical voltage 35
8.4.11 Interferents 36
8.4.12 Averaging test 36
8.4.13 Difference sample/calibration port 37
8.4.14 Residence time in the analyser 38
8.5 Determination of the performance characteristics during the field test 38
8.5.1 General 38
8.5.2 Selection of a monitoring station for the field test 38
8.5.3 Operational requirements 39
8.5.4 Long-term drift 40
8.5.5 Reproducibility standard deviation under field conditions 40
8.5.6 Period of unattended operation 41
8.5.7 Period of availability of the analyser 41
8.6 Type testing and uncertainty calculation 42

9 Field operation and ongoing quality control 42
9.1 General 42
9.2 Suitability evaluation 43
9.2.1 General 43
9.2.2 Analyser for a monitoring station or task 43
9.3 Initial installation 44
9.4 Ongoing quality assurance/quality control 46
9.4.1 General 46
9.4.2 Frequency of calibrations, checks and maintenance 47
9.5 Calibration of the analyser 50
9.5.1 General 50
9.5.2 Calibration gases 51
9.5.3 Data adjustment function 51
9.5.4 Testing the sampling system 51
9.5.5 Treatment of data after exceedance of performance criteria 53
9.6 Checks 55
9.6.1 Zero and span checks 55
9.6.2 Lack of fit 56
9.6.3 Testing the sample manifold 57
9.7 Maintenance 58
9.7.1 Change of particle filters 58
9.7.2 Maintenance of sampling system 58
9.7.3 Change of consumables as applicable 58
9.7.4 Preventive/routine maintenance of components of the analyser 58
9.8 Data handling and data reports 59
9.9 Measurement uncertainty 59

10 Expression of results 59

11 Test reports and documentation 60
11.1 Type testing 60
11.2 Field operation 61
11.2.1 Suitability evaluation 61
11.2.2 Documentation 61
11.2.3 Ambient air quality data reports 61

Annex A (normative) Test of lack of fit 63

A.1 Establishment of the regression line 63
A.2 Calculation of the residuals of the averages 64

Annex B (informative) Sampling equipment 65

Annex C (informative) Ultraviolet photometric analyser 67

Annex D (informative) Manifold testing 69

D.1 Procedure for applying test gas 69
D.2 Procedure for the cross test 70
D.2.1 General 70
D.2.2 Initial stage 70
D.2.3 Stage 1 71
D.2.4 Stage 2 71
D.2.5 Data Processing 71
D.2.6 Evaluation 71

Annex E (normative) Type testing 73

E.1 Type testing and uncertainty calculation 73
E.1.1 Type testing 73
E.1.2 Uncertainty calculation 73
E.2 Type testing Requirement a) 73
E.3 Type testing Requirement b) 75
E.3.1 General 75
E.3.2 Calculation of standard uncertainties 78
E.3.2.1 General 78
E.3.2.2 Repeatability at zero 78
E.3.2.3 Repeatability at the hourly alert threshold value of ozone 78
E.3.2.4 Lack of fit 79
E.3.2.5 Influence quantities 79
E.3.2.5.1 General 79
E.3.2.5.2 Sample gas pressure 80
E.3.2.5.3 Sample gas temperature 80
E.3.2.5.4 Surrounding temperature 80
E.3.2.5.5 Electrical voltage 81
E.3.2.5.6 Water vapour 81
E.3.2.5.7 Other interferents 82
E.3.2.5.8 Averaging effect 83
E.3.2.5.9 Calibration gas 83
E.3.2.5.10 Difference sample/calibration port 83
E.3.3 Example calculation 84
E.4 Type testing Requirement c) 85
E.5 Type testing Requirement d) 85
E.5.1 General 85
E.5.2 Combined standard uncertainty 87
E.5.3 Absolute expanded uncertainty 87
E.5.4 Relative expanded uncertainty 87
E.5.5 Calculation of standard uncertainties 88
E.5.6 Example calculation 90

Annex F (informative) Calculation of uncertainty in field operation at the hourly alert threshold value 92

F.1 General 92
F.2 Combined standard uncertainty 92
F.3 Standard uncertainties 93
F.3.1 General 93
F.3.1.1 Introduction 93
F.3.1.2 Repeatability at zero 93
F.3.1.3 Repeatability at the hourly alert threshold value 93
F.3.1.4 Lack of fit 93
F.3.2 Influence quantities 94
F.3.2.1 General 94
F.3.2.2 Sample gas pressure 94
F.3.2.3 Sample gas temperature 94

F.3.2.4 Surrounding temperature ... 95
F.3.2.5 Electrical voltage ... 96
F.3.3 Interferents ... 96
F.3.3.1 General ... 96
F.3.3.2 Water vapour ... 96
F.3.3.3 Other interferents ... 97
F.3.4 Averaging effect ... 97
F.3.5 Reproducibility under field conditions ... 97
F.3.6 Long-term drift at zero ... 97
F.3.7 Long-term drift at level of the hourly alert threshold value ... 98
F.3.8 Zero gas ... 98
F.3.9 Calibration gas ... 98
F.3.10 Difference sample/calibration port ... 98
F.4 Example calculation ... 99

Annex G (informative) Calculation of uncertainty in field operation at the 8-hour target value ... 101

G.1 General ... 101
G.2 Combined standard uncertainty ... 101
G.3 Standard uncertainties ... 102
G.3.1 General ... 102
G.3.1.1 Introduction ... 102
G.3.1.2 Repeatability at zero ... 102
G.3.1.3 Repeatability at the 8-hour target value ... 103
G.3.1.4 Lack of fit ... 103
G.3.2 Influence quantities ... 103
G.3.2.1 General ... 103
G.3.2.2 Sample gas pressure ... 104
G.3.2.3 Sample gas temperature ... 104
G.3.2.4 Surrounding temperature ... 105
G.3.2.5 Electrical voltage ... 105
G.3.3 Interferents ... 106
G.3.3.1 General ... 106
G.3.3.2 Water vapour ... 106
G.3.3.3 Other interferents ... 107
G.3.4 Averaging effect ... 108
G.3.5 Zero gas ... 108
G.3.6 Calibration gas ... 108
G.3.7 Difference sample/calibration port ... 108
G.3.8 Reproducibility under field conditions ... 108
G.3.9 Long-term drift at zero ... 109
G.3.10 Long-term drift at level of the 8-hour target value ... 109
G.4 Example calculation ... 110

Annex H (informative)Test stand for the test point "sensitivity coefficient of sample gas pressure" 112

Annex I (informative) Significant changes ... 113

Bibliography ... 114