DIN EN 14626:2026-10 (E)

Ambient air - Standard method for the measurement of the concentration of carbon monoxide by non-dispersive infrared spectroscopy

Contents

Page

European foreword 5

1 Scope 6

2 Normative references 7

3 Terms and definitions 8

4 Abbreviated terms 13

5 Principle 13
5.1 General 13
5.2 Measuring principle 13
5.3 Type testing 14
5.4 Field operation and quality control 14

6 Sampling 15
6.1 General 15
6.2 Sampling location 15
6.3 Sampling system 15
6.3.1 Construction 15
6.3.2 Particle filter 16
6.3.3 Loss of carbon monoxide 16
6.3.4 Conditioning 16
6.4 Control and regulation of sample flow rate 16
6.5 Sampling pump for the manifold 17

7 Analyser equipment 17
7.1 General 17
7.2 Details about analyser equipment 17
7.3 Pressure measurement 17
7.4 Flow rate indicator 17
7.5 Sampling pump for the analyser 18
7.6 Particle filter 18

8 Type testing of carbon monoxide analysers 18
8.1 General 18
8.2 Relevant performance characteristics and performance criteria 19
8.3 Design change 23
8.4 Procedures for determination of the performance characteristics during the laboratory test 23
8.4.1 General 23
8.4.2 Test conditions 23
8.4.3 Response time 26
8.4.4 Short-term drift 28
8.4.5 Repeatability standard deviation 28
8.4.6 Lack of fit of linearity of the calibration function 29
8.4.7 Sensitivity coefficient to sample gas pressure 30
8.4.8 Sensitivity coefficient to the sample gas temperature 31
8.4.9 Sensitivity coefficient to the surrounding temperature 31
8.4.10 Sensitivity coefficient to electrical voltage 32

8.4.11 Interferents ... 33
8.4.12 Averaging test ... 34
8.4.13 Difference sample/calibration port ... 35
8.5 Determination of the performance characteristics during the field test ... 36
8.5.1 General ... 36
8.5.2 Selection of a monitoring station for the field test ... 36
8.5.3 Operational requirements ... 37
8.5.4 Long-term drift ... 38
8.5.5 Reproducibility standard deviation under field conditions ... 39
8.5.6 Period of unattended operation ... 39
8.5.7 Period of availability of the analyser ... 39
8.6 Expanded uncertainty calculation for type testing ... 40

9 Field operation and ongoing quality control ... 41
9.1 General ... 41
9.2 Suitability evaluation ... 41
9.2.1 General ... 41
9.2.2 Analyser for a monitoring station or task ... 41
9.3 Initial installation ... 43
9.4 Ongoing quality assurance/quality control ... 43
9.4.1 General ... 43
9.4.2 Frequency of calibrations, checks and maintenance ... 44
9.5 Calibration of the analyser ... 47
9.5.1 General ... 47
9.5.2 Calibration gases ... 48
9.5.3 Data adjustment function ... 48
9.5.4 Testing the sampling system ... 48
9.5.5 Treatment of data after exceedance of performance criteria ... 50
9.6 Checks ... 52
9.6.1 Zero and span checks ... 52
9.6.2 Lack-of-fit ... 53
9.6.3 Testing the sampling system ... 54
9.7 Maintenance ... 56
9.7.1 Change of particle filters ... 56
9.7.2 Maintenance of sampling system ... 56
9.7.3 Change of consumables as applicable ... 56
9.7.4 Preventive/routine maintenance of components of the analyser ... 56
9.8 Data handling and data reports ... 56
9.9 Measurement uncertainty ... 57

10 Expression of results ... 57

11 Test reports and documentation ... 58
11.1 Type testing ... 58
11.2 Field operation ... 59
11.2.1 Suitability evaluation ... 59
11.2.2 Documentation ... 59
11.2.3 Ambient air quality data reports ... 60

Annex A (normative) Test of lack-of-fit ... 61

A.1 Establishment of the regression line ... 61
A.2 Calculation of the residuals of the averages ... 61

Annex B (informative) Sampling equipment ... 63

Annex C (informative) Schematics of non-dispersive infrared spectrometer ... 65

Annex D (informative) Manifold testing ... 67

D.1 Procedure for applying test gas ... 67
D.2 Procedure for the cross test ... 68

D.2.1 General 68
D.2.2 Initial stage 68
D.2.3 Stage 1 69
D.2.4 Stage 2 69
D.2.5 Data Processing 69
D.2.6 Evaluation 69

Annex E (normative) Type testing 71

E.1 Type testing and uncertainty calculation 71
E.1.1 Type testing 71
E.1.2 Uncertainty calculation 71
E.2 Type testing Requirement a) 71
E.3 Type testing Requirement b) 73
E.3.1 General 73
E.3.2 Calculation of standard uncertainties 76
E.3.3 Example calculation 83
E.4 Type testing Requirement c) 85
E.5 Type testing Requirement d) 85
E.5.1 General 85
E.5.2 Combined standard uncertainty 87
E.5.3 Absolute expanded uncertainty 87
E.5.4 Relative expanded uncertainty 88
E.5.5 Calculation of standard uncertainties 88
E.5.6 Example calculation 90

Annex F (informative) Calculation of uncertainty in field operation at the 8-hour limit value 92

F.1 General 92
F.2 Combined standard uncertainty 92
F.3 Standard uncertainties 93
F.3.1 General 93
F.3.2 Influence quantities 94
F.3.3 Interferents 97
F.3.4 Averaging effect 98
F.3.5 Reproducibility under field conditions 98
F.3.6 Long-term drift at zero 98
F.3.7 Long-term drift at level of the 8-hour limit value 98
F.3.8 Zero gas 99
F.3.9 Calibration gas 99
F.3.10 Difference sample/calibration port 99
F.4 Example calculation 100

Annex G (informative) Test stand for the test point "sensitivity coefficient of sample gas pressure" 102

Annex H (informative) Significant changes 104

Bibliography 105