ISO 11338-2:2003-06 (E)

Stationary source emissions - Determination of gas and particle-phase polycycli c aromatic hydrocarbons - Part 2: Sample preparation, clean-up and determination

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 2
4.1 Sampling 2
4.2 Analysis 2

5 Safety measures 2

6 Procedures 2
6.1 HPLC method 2
6.2 GC-MS method 9

7 Limitations and interferences 16
7.1 Limitations 16
7.2 Interferences 17

Annex A (informative) Maximum UV absorption wavelength and recommended combinations of excitation-emission wavelengths for HPLC 18

Annex B (informative) Formulae and physical properties of selected PAH 19

Annex C (informative) Characteristic ions for GC-MS detection of selected PAH, recovery, and surrogate recovery standards 20

Annex D (informative) Applicability of internal standards for GC-MS detection of selected PAH 21

Annex E (normative) Summary of performance characteristics of the HPLC method 22

Bibliography 23