# DIN EN 1948-2:2006-06 (E)

## Stationary source emissions - Determination of the mass concentration of PCDDs/PCDFs and dioxin-like PCBs - Part 2: Extraction and clean-up of PCDDs/PCDFs

## Contents

Page


Foreword ....3

Introduction ....6

1 Scope ....7

2 Normative references ....7

3 Terms and definitions ....7

4 Symbols and abbreviations ....10

5 Principle of the extraction and clean-up procedure ....11

6 Device, materials and 13 C12-labelled standards ....12

7 Method validation and quality control requirements ....13

8 Sample pre-treatment and extraction ....14

9 Report ....16

Annex A (informative) Examples of operation of extraction and clean-up methods ....17

Annex B (informative) Relations to EU Directives ....35

Bibliography ....36