DIN EN 1948-3:2006-06 (E)

Stationary source emissions - Determination of the mass concentration of PCDDs/PCDFs and dioxin-l ike PCBs - Part 3: Identification and quantification of PCDDs/PCDFs

Contents

Page

Foreword 3

Introduction 6

1 Scope 7

2 Normative references 7

3 Terms and definitions 7

4 Symbols and abbreviations 10

5 Principles of identification and quantification 11

6 Reagents, materials and equipment 11

7 Safety measures 11

8 Quality control requirements for identification and quantification 11

9 Quality assurance criteria for extraction/clean-up/quantification procedure blanks 13

10 Calibration of the HRGC/HRMS 14

11 Quantification of HRGC/HRMS results 15

12 Calculation of the measurement results 18

13 Analytical report 18

14 Performance characteristics 19

15 Interferences 21

Annex A (informative) Examples of operation of gas chromatography / mass spectrometry analysis of PCDDs/PCDFs in emission samples 22

Annex B (informative) Estimation of the measuring uncertainty and precision of the determination of polychlorinated dibenzo-p-dioxins and dibenzofurans 31

Annex C (informative) Mass of ions monitored for PCDDs and PCDFs 35

Annex D (informative) Relative abundance of chlorine isotope ions and their ratio for PCDD/PCDF congeners containing 4 to 8 chlorine substituents 36

Annex E (informative) Further general recommendations for separation, detection and quantification of PCDDs/PCDFs 37

Annex F (informative) Variability determination based on the results of the validation tests 39

Annex G (informative) Relation to EU Directives 47

Bibliography 48