DIN EN ISO 16474-2:2014-03 (E)

Paints and varnishes - Methods of exposure to laboratory light sources - Part 2: Xenon-arc lamps (ISO 16474-2:2013)

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Termsanddefinitions 5

4 Principle 6

5 Apparatus 7
5.1 Laboratory light source 7
5.2 Test chamber 8
5.3 Radiometer 9
5.4 Black-standard/black-panel thermometer 9
5.5 Wetting and humidity-control equipment 9
5.6 Specimen holders 9
5.7 Apparatus to assess changes in properties 10

6 Test specimens 10

7 Exposure conditions 10
7.1 Radiation 10
7.2 Temperature 10
7.3 Relative humidity of chamber air 11
7.4 Spray cycle 12
7.5 Cycles with dark periods 12
7.6 Sets of exposure conditions 13

8 Procedure 13
8.1 General 13
8.2 Mounting the test specimens 13
8.3 Exposure 13
8.4 Duration of test 14
8.5 Measurement of radiant exposure 14
8.6 Determination of changes in properties after exposure 14

9 Test report 14

Annex A (informative) Filtered xenon-arc radiation -- Spectral power distribution 15

Annex B (normative) Additional exposure cycles 17

Bibliography 19