ISO 2811-1:2016-03 (E)

Paints and varnishes - Determination of density - Part 1: Pycnometer method

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Principle 1

5 Temperature 1

6 Apparatus 2

7 Sampling 2

8 Procedure 2
8.1 General 2
8.2 Determination 3

9 Calculation 4

10 Precision 4
10.1 Repeatability limit, r 4
10.2 Reproducibility limit, R 4

11 Test report 4

Annex A (informative) Example of a calibration method 6

Annex B (informative) Temperature variation 8

Bibliography 10