ISO 8130-1:2019 (E)

Coating powders — Part 1: Determination of particle size distribution by sieving

Contents

Foreword

1 Scope

2 Normative references

3 Terms and definitions

4 Principle

5 Apparatus

6 Sampling

7 Choice of sieving method and sieve selectivity

8 Preparation of the test sieve

9 Procedure

- 9.1 Number of determinations
- 9.2 Manual sieving (with mesh sizes greater than 100 µm)
- 9.3 Machine sieving using an air-jet sieve apparatus
- 9.4 Machine sieving using vibration mechanism

10 Expression of results

11 Precision

12 Test report

Annex A (informative) Nominal sizes of test sieves

Page count: 9