ISO 8502-6:2020-04 (E)

Preparation of steel substrates before application of paints and related products - Tests for the assessment of surface cleanliness - Part 6: Extraction of water soluble contaminants for analysis (Bresle method)

Contents

Page

Foreword ... iv

Introduction ... v

1 Scope ... 1

2 Normative references ... 1

3 Terms and definitions ... 1

4 Principle ... 2

5 Apparatus and materials ... 2

6 Procedure ... 3

6.1 Selection of test surface ... 3

6.2 Blank test ... 3

6.3 Extraction by patch or sleeve by injection ... 3

6.4 Extraction by sleeve by pre-filling ... 5

7 Analyses ... 5

8 Test report ... 5

Annex A (normative) **Leak test for type testing of adhesive cells (patches and sleeves)** ... 9

Bibliography ... 11