DIN CEN/TR 16369:2014-04 (E)

Use of control charts in the production of concrete; English version CEN/TR 16369:2012

Contents

Page

Foreword 4

Introduction 5

1 Scope 7

2 Symbols and abbreviations 7

3 Statistics for Concrete 8
3.1 Normal distribution of strength 8
3.2 Characteristic strength and target strength 8
3.3 Standard deviation 10
3.4 Setting the target strength 13

4 Simple Data Charts 14

5 Shewhart Charts 15
5.1 Introduction 15
5.2 Shewhart action criteria 16
5.2.1 Points beyond UCL or LCL 16
5.2.2 Points beyond UWL or LWL 16
5.2.3 Patterns within control limits 16
5.3 Control of standard deviation 16
5.4 Example Shewhart chart 16
5.5 Modified application of Shewhart control chart 17

6 CUSUM 19
6.1 Introduction 19
6.2 Controlling mean strength 22
6.3 Controlling standard deviation 22
6.4 Controlling correlation 23
6.5 Design of V-mask 24
6.6 Action following change 24

7 Multivariable and Multigrade Analysis 26
7.1 General 26
7.2 Multivariable 26
7.3 Multigrade 27

8 Speeding the Response of the System 28
8.1 Early age testing 28
8.2 Family of mixes concept 28

9 Guidance on Control Systems 30
9.1 Abnormal Results 30
9.2 Handling mixes outside the concrete family 30
9.3 Handling mixes not controlled by compressive strength requirements 31
9.4 Test rates 32
9.5 Action following change 33

10 EN 206-1 Conformity Rules for Compressive Strength 33

10.1 Basic requirements for conformity of compressive strength 33
10.2 Assessment period 34
10.3 Conformity rules for compressive strength 34
10.4 Achieving an AOQL of 5 % with CUSUM 36
10.5 Non-conformity 37

11 Implementing Control Systems 38

12 CUSUM Example 38
12.1 Reference mix and concrete family 38
12.2 Main relationship 39
12.3 Applying adjustments 40
12.4 CUSUM calculation 41
12.5 CUSUM action following change 45
12.6 Further data and a change in standard deviation 47

Bibliography 51