ISO 5660-1:2015-03 (E)

Reaction-to-fire tests - Heat release, smoke production and mass loss rate - Part 1: Heat release rate (cone calorimeter method) and smoke production rate (dynamic measurement)

Contents

Page

Foreword v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols 3

5 Principle 4

6 Apparatus 5
6.1 General 5
6.2 Cone-shaped radiant electrical heater 5
6.3 Radiation shield 5
6.4 Irradiance control 5
6.5 Weighing device 5
6.6 Specimen holder 6
6.7 Retainer frame 6
6.8 Exhaust gas system with flow measuring instrumentation 6
6.9 Gas sampling apparatus 6
6.10 Ignition circuit 7
6.11 Ignition timer 7
6.12 Oxygen analyser 7
6.13 Heat flux meters 7
6.14 Calibration burner 7
6.15 Data collection and analysis system 8
6.16 Optional side screens 8
6.17 Smoke obscuration measuring system 8
6.18 Smoke system thermocouple 8
6.19 Optical filters 8

7 Suitability of a product for testing 9
7.1 Surface characteristics 9
7.2 Asymmetrical products 9
7.3 Materials of short burning time 9
7.4 Composite specimens 9
7.5 Dimensionally unstable materials 9
7.6 Materials that require testing under compression 10

8 Specimen construction and preparation 10
8.1 Specimens 10
8.2 Conditioning of specimens 10
8.3 Preparation 11
8.3.1 Specimen wrapping 11
8.3.2 Specimen preparation 11
8.3.3 Preparing specimens of materials that require testing under compression 11

9 Test environment ... 11

10 Calibration ... 12
10.1 Preliminary calibrations ... 12
10.1.1 General ... 12
10.1.2 Irradiance control system response characteristics ... 12
10.1.3 Weighing device response time ... 12
10.1.4 Weighing device output drift ... 12
10.1.5 Oxygen analyser delay and response times ... 12
10.1.6 Oxygen analyser output noise and drift ... 13
10.1.7 Effect of side screens ... 13
10.2 Operating calibrations ... 14

10.2.1 General ... 14
10.2.2 Weighing device accuracy ... 14
10.2.3 Oxygen analyser ... 14
10.2.4 Heat release rate calibration ... 14
10.2.5 Heater calibration ... 15
10.3 Smoke meter calibration ... 15
10.3.1 Calibration with neutral density filters ... 15
10.3.2 Calibration before test ... 15
10.4 Less frequent calibrations ... 15
10.4.1 Operating heat flux meter calibration ... 15
10.4.2 Linearity of heat release rate measurements ... 15
10.4.3 Accuracy of calibration burner flow meter ... 15

11 Test procedure ... 16
11.1 General precautions ... 16
11.2 Initial preparation ... 16
11.3 Procedure ... 16

12 Calculations ... 17
12.1 General ... 17
12.2 Calibration constant for oxygen consumption analysis ... 18
12.3 Heat release rate ... 18
12.4 Exhaust duct flow rate ... 18
12.5 Mass loss rate ... 19
12.6 Smoke obscuration ... 19

13 Test report ... 20

Annex A (informative) Commentary and guidance notes for operators ... 31

Annex B (informative) Supplementary calculations -- Normalization to the mass loss rate of the specific extinction area of specimen ... 36

Annex C (informative) Resolution, precision and bias ... 38

Annex D (informative) Mass loss rate and effective heat of combustion ... 44

Annex E (informative) Testing in the vertical orientation ... 45

Annex F (informative) Calibration of the working heat flux meter ... 48

Annex G (informative) Calculation of heat release with additional gas analysis ... 49

Annex H (informative) Calculation of Effective Critical Heat Flux for Ignition ... 53

Bibliography ... 54