# ISO 19430:2016-12 (E)

## Particle size analysis - Particle tracking analysis (PTA) method

## Contents

Page


Foreword ..... iv

Introduction ..... v

1 Scope ..... 1

2 Normative references ..... 1

3 Termsanddefinitions ..... 1

4 Symbols and abbreviated terms ..... 4

5 Principles ..... 4
5.1 General ..... 4
5.2 Key physical parameters ..... 5
5.3 Detection limits ..... 5
5.3.1 Lower size limit ..... 5
5.3.2 Upper size limit ..... 6
5.3.3 Sample and sampling volume ..... 6
5.3.4 Maximum particle number concentration ..... 6
5.3.5 Minimum particle number concentration ..... 7
5.4 Measurement precision and uncertainties ..... 7
5.4.1 General ..... 7
5.4.2 Measurement precision ..... 7
5.4.3 Size range ..... 8
5.4.4 Counting efficiency ..... 8
5.4.5 Sizing accuracy ..... 9
5.4.6 Size resolution ..... 9

6 Apparatus ..... 10

7 Procedure ..... 11
7.1 General ..... 11
7.2 Sample preparation ..... 12
7.3 Instrument set-up and initialisation ..... 12
7.4 Measurement ..... 13
7.4.1 Sample delivery ..... 13
7.4.2 Sample illumination ..... 13
7.4.3 Particle imaging and tracking ..... 14
7.4.4 Track analysis ..... 14
7.5 Results evaluation ..... 14
7.5.1 General ..... 14
7.5.2 Particle size evaluation ..... 14
7.5.3 Distribution analysis ..... 14
7.5.4 Data analysis and reporting ..... 14

8 Systemqualificationandqualitycontrol ..... 15
8.1 General ..... 15
8.2 System installation requirements ..... 15
8.3 System maintenance ..... 15
8.4 System operation ..... 15
8.5 System qualification ..... 16

9 Data recording ..... 17

10 Test report ..... 17

Annex A (informative) Theory ..... 20

Annex B (informative) Apparatus settings and best practice ..... 23

Bibliography ..... 25