DIN 66165-1:2022-06 (E)

Particle size analysis - Sieving analysis - Part 1: Fundamentals

Contents

Page

Foreword 3

1 Scope 4

2 Normative references 4

3 Terms and definitions 4

4 Methods of test sieving 4

5 Factors affecting test sieving 5
5.1 General 5
5.2 Equipment- and process-related factors 6
5.2.1 Size and shape of sieve openings, distribution of sieve openings 6
5.2.2 Effective sieving area 6
5.2.3 Movement of sieve or fluid 6
5.2.4 Sieving aids 6
5.2.5 Sieving using a set of test sieves 6
5.3 Material-related factors: 6
5.3.1 Mass and bulk volume of the material to be sieved (sample) 6
5.3.2 Particle size distribution 8
5.3.3 Shape of particles 8
5.3.4 Tendency to agglomerate and to cohere 8
5.3.5 Susceptibility to abrasion and fracture 8
5.4 Sieving time 8

6 Determination of cut point 9

7 Selecting the sieve openings 10

8 Analytical errors 10

9 Checking and maintenance of the test sieves 10

10 Calibration using reference material 11
10.1 Requirements to be met by the reference material 11
10.2 Calibration procedure 12

11 Determining the distribution of the sieve opening sizes 12

Bibliography 13

Figures Figure 1 -- Plot of sieving time as a function of d d 9

Tables Table 1 -- Methods of sieve analysis 5

Table 2 -- Maximum permissible bulk volume of the oversize as a function of opening size 7