ISO 17123-3:2001-12 (E)

Optics and optical instruments - Field procedures for testing geodetic and surveying instruments - Part 3: Theodolites

Contents

Page

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 General 2

5 Measurement of horizontal directions 3

6 Measurement of vertical angles 8

Annexes A Example of the simplified test procedure (horizontal directions) 12

A.1 Measurements 12
A.2 Calculation 12

B Example of the full test procedure (horizontal directions) 14
B.1 Measurements 14
B.2 Calculation 15
B.3 Statistical tests 16

C Example of both test procedures (vertical angles) 18
C.1 Measurements 18
C.2 Calculation 19
C.3 Statistical tests 20