DIN EN ISO 13732-1:2008-12 (E)

Ergonomics of the thermal environment - Methods for the assessment of human responses to contact with su rfaces - Part 1: Hot surfaces (ISO 13732-1:2006)

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 6

3 Terms and definitions 6

4 Burn thresholds 7
4.1 General 7
4.2 Burn threshold data 8

5 Assessment of risk of burning 14
5.1 Procedure 14
5.2 Identification of hot, touchable surfaces 14
5.3 Task analysis 15
5.4 Measurements of surface temperatures 15
5.5 Choice of applicable burn threshold value 16
5.6 Comparison of surface temperature and burn threshold 17
5.7 Determination of risk of burning 18
5.8 Repetition 18

6 Protective measures 19
6.1 General 19
6.2 No risk of burning 19
6.3 Risk of burning 19

7 Guidance for setting surface temperature limit values 20
7.1 Procedure 20
7.2 Assessment of risk of burning 20
7.3 Decision upon protective measures 20
7.4 Selection of appropriate values 20
7.5 Setting of surface temperature limit value 21

Annex A (informative) Scientific background 22

Annex B (normative) Contact periods 24

Annex C (informative) Flow charts for application of this part of ISO 13732 25

Annex D (informative) Thermal properties of selected materials 27

Annex E (informative) Examples of protective measures against burns 28

Annex F (informative) Example for assessment of risk of burning 30

Annex G (informative) Examples for setting surface temperature limit values 35

Annex ZA (informative) Relationship between this European Standard and the Essential Annex ZB (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC 41

Requirements of EU Directive 2006/42/EC 42

Bibliography 43

Annex H (informative) Safety signs for hot surfaces 39