ISO 13779-3:2008-02 (E)

Implants for surgery - Hydroxyapatite - Part 3: Chemical analysis and characterization of crystallinity and phase purity

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms, definitions and symbols 1
3.1 Terms and definitions 1
3.2 Symbols 2

4 Analytical methods 2

5 Apparatus, reagents and calibration specimens 2
5.1 Apparatus for chemical analysis 2
5.2 Reagents for chemical analysis 3
5.3 Apparatus and calibration specimens for X-ray diffraction analysis 3
5.4 Infrared apparatus 4

6 X-Ray diffraction pattern collection 4
6.1 General 4
6.2 Identification of the crystallized phases 4

7 Preparation of the test sample 5
7.1 Coatings 5
7.2 Bulk sample 5
7.3 X-ray analysis 5

8 Plotting the calibration curves 6
8.1 General 6
8.2 Plotting the calibration curves for the foreign phases 6
8.3 Plotting the calibration curves for the calculation of the calcium:phosphorus (Ca:P) ratio 7

9 Chemical analysis 8
9.1 General 8
9.2 Expression of results 8

10 Ca:P ratio 8
10.1 General 8
10.2 Procedure 9
10.3 Measurements on the sample 9
10.4 Choice of the diffraction peaks 9
10.5 Expression of results 9
11 Qualitative and quantitative determination of the foreign phases 10
11.1 Procedure 10
11.2 Expression of results 10
12 Determination of the crystallinity ratio 10
12.1 General 10
12.2 Preparation of the sample 10

12.3 Procedure 10
12.4 Expression of results 10
13 Degradation of ceramics 11
14 Test report 11

Annex A (informative) Contamination of calcium phosphate 12

Annex B (normative) Testing of the purity of the phases used in the production of the calibration curves 13

Annex C (informative) Examples of X-ray diffraction patterns collected from various mixtures used to plot the calibration curves 14

Annex D (normative) Positions of lines used to measure the crystallinity ratio 16

Annex E (informative) Examples of methods for the preparation of reference materials 17

Bibliography 19