ISO/TR 21254-4:2011-09 (E)

Lasers and laser-related equipment - Test methods for laser-induced damage threshold - Part 4: Inspection, detection and measurement

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Damage detection methods 1
4.1 General 1
4.2 Summary of damage detection methods 2
4.3 Collection of radiation from the sample 3
4.3.1 Scatter detection techniques 3
4.3.2 Detection of plasma and thermal radiation 4
4.3.3 Fluorescence 4
4.4 Detection of changes in reflectance or transmittance and imaging techniques 5
4.4.1 Online detection of changes in reflectance or transmittance 5
4.4.2 Online microscopy 7
4.5 Photothermal detection schemes 8
4.5.1 General 8
4.5.2 Photothermal deflection and surface thermal lensing 8
4.5.3 Mirage effect 10
4.6 Transient pressure sensing 10

5 Inspection techniques after the laser test sequence 11
5.1 General 11
5.2 Nomarski microscopy 12
5.3 Microscopic image comparator 12
5.4 Laser scanning microscopy 14
5.5 Mapping techniques 15
5.6 Electron microscopy 16
5.7 Atomic force microscopy 17
5.8 Confocal microscopy 17

Bibliography 19