DIN ISO 9022-22:2012-10 (E)

Optics and photonics - Environmental test methods - Part 22: Combined cold, dry heat or temp erature change with bump or random vibration (ISO 9022-22:2012)

Contents

Page

National foreword 3

National Annex NA (informative) Bibliography 4

Introduction 5

1 Scope 6

2 Normative references 6

3 Terms and definitions 6

4 General information and test conditions 6

5 Conditioning 7
5.1 General 7
5.2 Conditioning method 22: Cold, dry heat or temperature change combined with bump or random vibration 7

6 Procedure 8
6.1 General 8
6.2 Test sequence with cold or dry heat testing 8
6.3 Test sequence with temperature change 8
6.4 Operating condition of specimen 8
6.5 Mechanical conditioning of specimen 9

7 Environmental test code 9

8 Specification 10

Annex A (informative) Explanatory notes 11

Bibliography 12