ISO 9335:2012-10 (E)

Optics and photonics - Optical transfer function - Principles and procedures of measurement

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Measuring equipment and environment 1
4.1 General aspects 1
4.2 Environment 2
4.3 Measuring equipment 2
4.4 System components 3

5 Measurement procedures 10
5.1 General 10
5.2 Setting the measuring conditions 10
5.3 Additional considerations of measurement 11
5.4 Particular measuring conditions 13

6 Corrections to measured data 14
6.1 Normalization 14
6.2 Correction of the frequency scale 14
6.3 Correction of the measured modulation 14
6.4 Auxiliary imaging systems 15

7 Presentation of OTF data 15
7.1 General 15
7.2 Statementofidentificationandmeasuringconditions 15
7.3 Graphical presentation of OTF data 16
7.4 Numerical presentation 17

8 Accuracy checks 17

Annex A (informative) Examples of the presentation of OTF data 19

Bibliography 24