ISO 9022-2:2015-03 (E)

Optics and photonics - Environmental test methods - Part 2: Cold, heat and humidity

Contents

Page

Foreword ..... **iv**

Introduction ..... **vi**

1 Scope **1**

2 Normative references **1**

3 General information and test conditions **1**

4 Conditioning **1**

4.1 General 1

4.2 Constant stress conditions 2

4.2.1 General 2

4.2.2 Conditioning method 10: Cold 2

4.2.3 Conditioning method 11: Dry heat 2

4.2.4 Conditioning method 12: Damp heat 2

4.2.5 Conditioning method 13: Condensation 2

4.3 Cycling exposure conditions 3

4.3.1 General 3

4.3.2 Conditioning method 14: Slow temperature change 3

4.3.3 Conditioning method 15: Rapid temperature change (temperature shock) 4

4.3.4 Conditioning method 16: Damp heat, cyclic 5

5 Procedure **7**

5.1 General 7

5.2 Pre-test 7

6 Environmental test code **7**

7 Specification **8**