DIN ISO 9022-8:2015-08 (E)

Optics and photonics - Environmental test methods - Part 8: High internal pressure, low internal pressure, immersion (ISO 9022-8:2015)

Contents

Page

National foreword ... **3**

National Annex NA (informative) **Bibliography** ... **4**

Introduction ... **5**

1 Scope ... **6**

2 Normative references ... **6**

3 General information and test conditions ... **6**

4 Conditioning ... **6**
4.1 Conditioning method 80: High internal pressure ... 6
4.2 Conditioning method 81: Low internal pressure ... 6
4.3 Conditioning method 82: Immersion ... 7

5 Procedure ... **7**
5.1 General ... 7
5.2 Conditioning method 82: Preconditioning of specimen and initial test ... 7
5.3 Conditioning methods 80 and 81: Pressure change curve ... 7
5.4 State of operation 2 ... 8
5.5 Conditioning method 82: Recovery and final test ... 8
5.6 Conditioning method 82: Evaluation ... 8

6 Environmental test code ... **8**

7 Specification ... **8**

Annex A (informative) **Explanatory notes** ... **10**