DIN ISO 9022-12:2016-02 (E)

Optics and photonics - Environmental test methods - Part 12: Contamination (ISO 9022-12:2015)

Contents

Page

National Foreword 3

National Annex NA (informative) **Bibliography** 4

Introduction 5

1 Scope 6

2 Normative references 6

3 General information and test conditions 6
3.1 Specimen 6
3.2 Test pad 7
3.3 Test weight and arrangement of test pads 8

4 Conditioning 9
4.1 General 9
4.2 Conditioning method 86: Basic cosmetic substances and artificial hand sweat 9
4.3 Conditioning method 87: Laboratory agents 9
4.4 Conditioning method 88: Production plant resources 9
4.5 Conditioning method 89: Fuels and resources for aircraft, naval vessels, and land vehicles 9

5 Procedure 12
5.1 General 12
5.2 Preconditioning 12
5.3 Test sequence 13
5.4 Recovery 13
5.5 Evaluation 13
5.6 General level for acceptance 13

6 Environmental test code 14

7 Specification 14

Annex A (normative) **Determination of pH value of aqueous extract of pad materials** 15