ISO 14243-2:2016-09 (E)

Implants for surgery - Wear of total knee-joint prostheses - Part 2: Methods of measurement

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Gravimetric method 1
4.1 Principle 1
4.2 Reagents and materials 1
4.3 Apparatus 2
4.4 Test and control specimens 2
4.5 Preparation of test and control specimens for gravimetric measurements (pre- soak conditioning) 2
4.6 Procedure for gravimetric measurement 3

5 Test report 3