ISO 10110-18:2018-12 (E)

Optics and photonics - Preparation of drawings for optical elements and systems - Part 18: Stress bi refringence, bubbles and inclusions, homogeneity, and striae

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1
3.1 Terms for stress birefringence 1
3.2 Terms for bubbles and inclusions 2
3.3 Terms for homogeneity and striae 2

4 Specificationofrawmaterialandfinishedassemblies 2
4.1 Raw material 2
4.2 Finished assemblies 2

5 Stress birefringence 3
5.1 Principle of specification 3
5.2 Indication in drawings 3
5.2.1 Indication codes 3
5.2.2 Structure of the indication 3
5.3 Examples of indications for stress birefringence 3

6 Bubbles and inclusions 3
6.1 General 3
6.2 Principle of specification 3
6.3 Indication in drawings 4
6.3.1 Indication codes 4
6.3.2 Structure of the indication 4
6.4 Accumulation rule 4
6.5 Concentration rule 5
6.6 Examples of indications for bubbles 5

7 Homogeneity and striae 5
7.1 General 5
7.2 Indication in drawings 5
7.2.1 Indication codes 5
7.2.2 Structure of the indication 6
7.3 Homogeneity 6
7.3.1 Principle of specification 6
7.3.2 Quality classes 6
7.3.3 Focus term 7
7.4 Striae 7
7.4.1 Principles of specification 7
7.4.2 Density classes for striae 7
7.4.3 Wavefront deviation classes for striae 7
7.4.4 Comparison of density and wavefront quality classes for striae 8
7.4.5 Multiple orthogonal directions 8
7.5 Examples of indications for homogeneity and striae 8

8 Indications for "no requirement" or "default" 9

9 Indications on drawings 9
9.1 Table field 9
9.2 Drawing field 9

10 Indications for other optical material tolerances 9

11 Examples of indications on drawings 9
11.1 Example 1: Raw material properties in the drawing region 9
11.2 Example 2: Finished part bubble specification 10

11.3 Example 3: Finished part, all three properties 10
11.4 Example 4: System example 11
11.5 Example 5: Tabulation example 11

Annex A (informative) Stress optical constant and stress birefringence 12

Annex B (informative) Guidance for stress birefringence in optical glass 13

Annex C (informative) Guidance for bubble grades in optical glass 15

Annex D (informative) Guidance for homogeneity in optical glass 18

Annex E (informative) Guidance for striae in optical glass 20

Bibliography 22