DIN ISO 10110-18:2019-09 (E)

Optics and photo nics - Preparation of drawings for optical elements and systems - Part 18: Stres s birefringence, bubbles and inclusions, homogeneity, and striae (ISO 10110-18:2 018)

Contents

Page

8 Indications for "no requirement" or "default" 16

9 Indications on drawings 16
9.1 Table field 16
9.2 Drawing field 16

10 Indications for other optical material tolerances 16

11 Examples of indications on drawings 16
11.1 Example 1: Raw material properties in the drawing region 16
11.2 Example 2: Finished part bubble specification 17
11.3 Example 3: Finished part, all three properties 17
11.4 Example 4: System example 18
11.5 Example 5: Tabulation example 18

Annex A (informative) Stress optical constant and stress birefringence 19

Annex B (informative) Guidance for stress birefringence in optical glass 20

Annex C (informative) Guidance for bubble grades in optical glass 22

Annex D (informative) Guidance for homogeneity in optical glass 25

Annex E (informative) Guidance for striae in optical glass 27

Bibliography 29