ISO/TR 14999-2:2019-07 (E)

Optics and photonics - Interferometric measurement of optical elements and optical systems - Part 2: Measurement and evaluation techniques

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Measurement objects 1
4.1 Surfaces 1
4.1.1 Boundary surfaces of optical components 1
4.1.2 Reflection degree 2
4.1.3 Roughness 2
4.1.4 Topology of the regions (discontinuous regions) 2
4.1.5 Continuity of the surface; gradient of the surface 2
4.1.6 Stiffness of mirrors; finite-element-calculations 3
4.1.7 Temperature homogeneity of mirrors 3
4.1.8 Examples of measurement objects 3
4.2 Optical components in transmission 3
4.2.1 Single-pass versus double-pass testing 3
4.2.2 Windows (wavefront aberrations in transmission) 3
4.2.3 Prisms (wavefront aberrations and angle error) 3
4.2.4 Influence of temperature on the refractive index 3
4.3 Optical systems 4
4.3.1 Single-pass versus double-pass testing 4
4.3.2 Examination in the pupil 4
4.3.3 Chromatic aberrations 4
4.4 Indirect examination of the function of optical elements 4
4.4.1 Examination with different wavelengths 4
4.4.2 Examination with different beam paths 4
4.4.3 Tolerance range 4

5 Hardware aspects of an interferometer and test environment 4
5.1 General 4
5.2 Construction principles and influences on the quality of measurements 6
5.2.1 General 6
5.2.2 Intrinsic instrument errors and the principle of common path 7
5.2.3 Optical compensation of errors 8
5.2.4 Mathematical compensation of errors 9
5.2.5 Contrast as a function of the irradiance in test and reference arm: methods to attain equilibrium in both arms 10
5.2.6 Contrast as a function of performance of the light source 14
5.3 Test environment 16
5.3.1 General 16
5.3.2 Influence of vibrations 17
5.3.3 Influence of gravity and support of the test piece 18

6 Methods for evaluating the optical path difference 20
6.1 General 20

6.2 Visual inspection of interferograms 20
6.2.1 General 20
6.2.2 Example 1 -- Fizeau interferometer 20
6.2.3 Example 2 -- Twyman-Green interferometer 24
6.3 Manual evaluation of interferograms 26
6.4 Phase measurements with temporal carrier 28
6.4.1 General 28
6.4.2 Heterodyne interferometry 29

6.4.3 Phase lock interferometry (PLI) 30
6.4.4 Synchronous detection and phase-shifting interferometry 30
6.5 Phase measurements with spatial carrier 34
6.5.1 Fringe analysis by Fourier transform operations 34
6.5.2 Spatially synchronous fringe analysis 35
6.6 Removal of phase ambiguities (phase unwrapping) 37
6.7 Registration of wavefronts; coordinate systems, coordinate system definition 38
6.8 Polynomial and other representations of wavefronts 39
6.8.1 Representation of phase data 39
6.8.2 Zernike polynomials for a circular boundary 40
6.8.3 Use of Zernike polynomials for an elliptical boundary 40
6.8.4 Zernike-Tatian polynomials for a circular shape with a central hole (annular) 41
6.8.5 Legendre polynomials for a rectangle boundary 41
6.8.6 Orthogonal functions on "unusual areas" 41

7 Testreportsandcalibrationcertificates 41
7.1 General 41
7.2 Content of test reports and calibration certificates 42
7.3 Test reports 42
7.4 Calibration certificates 43
7.4.1 Basics 43
7.4.2 Specification 43
7.4.3 Adjustment or repair 43
7.5 Opinions and interpretations 43
7.6 Electronic transmission of results 43
7.7 Format of reports and certificates 44
7.8 Amendments to test reports and calibration certificates 44

8 Data format 44

Annex A (informative) Orthogonal polynomials 45

Bibliography 62