ISO 13142:2021 (E)

Optics and photonics — Lasers and laser-related equipment — Cavity ring-down method for high-reflectance and high-transmittance measurements

Contents

Foreword

Introduction

1 Scope

2 Normative references

3 Terms and definitions

4 Symbols used and units of measure

5 Test principles

- 5.1 General
- 5.2 Decay time of initial cavity and reflectance of cavity mirrors
- 5.3 Decay time of test cavity and reflectance/transmittance of test sample
- 5.4 High reflectance/transmittance measurement with an optical feedback CRD technique

6 Preparation of test sample and measurement arrangement

- 6.1 Test sample
- 6.2 Laser source
- 6.3 Ring-down cavity
- 6.4 Detection unit
- 6.5 Data acquisition and processing
- 6.6 Environment

7 Test procedure

- 7.1 General
- 7.2 Measurement of decay time of initial cavity
- 7.3 Calculation of reflectance of cavity mirrors
- 7.4 Measurement of decay time of test cavity
- 7.5 Calculation of reflectance/transmittance of test sample
- 7.6 Assessments of the measurement

8 Main error factors

- 8.1 Influence of the instrumental response time on reflectance/transmittance measurement
- 8.1.1 General
- 8.1.2 Multi-parameter fitting method
- 8.1.3 Data truncation method
- 8.2 Measurement error of the reflectance of cavity mirrors
- 8.3 Measurement error of the reflectance/transmittance of test sample

9 Test report

Annex A (informative) Reflectance/transmittance reliability check experiment

- A.1 General
- A.2 Method

Annex B (informative) Test report

Page count: 17