ISO 11551:2026-08 (E)

Optics and photonics - Lasers and laser-related equipment - Test method for absorptance of optical laser components

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols and units of measure 1

5 Preparation of test sample and measuring arrangement 2

6 Characteristic features of the laser radiation 4

7 Test procedure 5
7.1 General 5
7.2 Calibration 5
7.2.1 Calibration of the radiant power signal 5
7.2.2 Calibration of the temperature signal 5
7.2.3 Calibration of the thermal response 5
7.2.4 Measurement of the background signal 6
7.3 Determining the absorptance 6

8 Evaluation 6
8.1 General 6
8.2 Elimination of drift 7
8.3 Exponential method 7
8.4 Pulse method 8

9 Test report 9

Annex A (informative) Effects changing absorptance 11

Annex B (informative)Influenceofsignaldistortions 14

Annex C (informative) Algorithm for parameterizing the temperature data 17

Bibliography 18