# ISO 23747:2007-07 (E)

## Anaesthetic and respiratory equipment - Peak expiratory flow meters for the assessment of pulmonary function in spontaneously breathing humans

## Contents

Page


Foreword ..... iv

Introduction ..... v

1 Scope ..... 1

2 Normative references ..... 1

3 Terms and definitions ..... 1

4 General requirements ..... 2
4.1 Safety for PEFMs that utilize electricity ..... 2
4.2 Mechanical safety for all PEFMs ..... 2

5 Identification, marking and documents ..... 2
5.1 Marking of the scale or display ..... 2
5.2 Marking of PEFM or packaging ..... 3
5.3 Instructions for use ..... 3
5.4 Technical description ..... 4

6 PEFM measurement range ..... 4

7 Performance requirements ..... 4
7.1 Error of measurement ..... 4
7.2 Linearity ..... 4
7.3 Resistance to flow ..... 5
7.4 Frequency response ..... 5

8 Dismantling and reassembly ..... 5

9 Effects of mechanical ageing ..... 5

10 Effects of dropping a hand-held PEFM ..... 5
11 Cleaning, sterilization and disinfection ..... 5
11.1 Re-usable PEFM and parts ..... 5
11.2 PEFM and parts delivered sterile ..... 6
12 Compatibility with substances ..... 6
13 Biocompatibility ..... 6

Annex A (informative) Rationale for tests and examples of test apparatus ..... 7

Annex B (normative) Determination of error, repeatability and resistance to PEFM output ..... 10

Annex C (normative) Determination of frequency response ..... 13

Annex D (normative) Test methods for determination of the effects of dismantling, ageing and dropping ..... 15

Annex E (informative) Environmental aspects ..... 17

Annex F (informative) Reference to the essential principals ..... 19

Bibliography ..... 22