ISO 16063-34:2019-12 (E)

Methods for the calibration of vibration and shock transducers - Part 34: Tes ting of sensitivity at fixed temperatures

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Uncertainty of measurement 2

5 Ambient conditions 3

6 Apparatus 3

7 Method 1: Determination of complex sensitivity using a laser interferometer 4
7.1 General 4
7.2 Method 5
7.2.1 Test procedure 5
7.2.2 Expression of results 5

8 Method 2: Determination of complex sensitivity using a reference transducer inside a temperature chamber 6
8.1 General 6
8.2 Method 6
8.2.1 Test procedure 6
8.2.2 Expression of results 7

9 Method 3: Determination of complex sensitivity using a reference transducer outside the temperature chamber 7
9.1 General 7
9.2 Method 8
9.2.1 Test procedure 8
9.2.2 Expression of results 9

10 Preferred amplitudes, frequencies and temperatures 9

11 Test report 10

Annex A (informative) Determination of the achieving time of setpoint temperature for a device under test 12

Annex B (informative) Evaluating uncertainty caused by temperature tolerance 14

Bibliography 16