ISO 16063-13:2001-12 (E)

Methods for the calibration of vibration and shock transducers - Part 13: Primary shock calibration using laser interferometry

Contents

Page

1 Scope 1

2 Normative references 1

3 Uncertainty of measurement 1

4 Requirements for apparatus 2
4.1 General 2
4.2 Shock machine based on rigid body motion of an anvil 2
4.3 Shock machine based on wave propagation inside a long thin bar 2
4.4 Seismic block(s) for shock machine and laser interferometer 4
4.5 Laser 4
4.6 Interferometer 4
4.7 Oscilloscope 7
4.8 Waveform recorder with computer interface 7
4.9 Computer with data-processing program 7
4.10 Filters 7
4.11 Other requirements 7

5 Ambient conditions 8

6 Preferred accelerations and pulse durations 8

7 Method 8
7.1 Test procedure 8
7.2 Data acquisition 9
7.3 Data processing 9

8 Reporting the calibration results 13

Annexes A Expression of uncertainty of measurement in calibration 14

B Explanation of the procedures 16

C Alternative method of calculation of magnitude and phase shift of the complex sensitivity 20

Bibliography 22