DIN EN 13042-3:2010-05 (E)

Machines and plants for the manufacture, treatment and processing of hollow glass - Safety requirements - Part 3: IS machines (includes Amendment A1:2009)

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 6

3 Terms and definitions 7

4 List of significant hazards 7

5 Safety requirements and/or protective measures 9
5.1 General 9
5.2 Starting and stopping and unexpected start-up 10
5.3 Emergency-stop equipment 10
5.4 Prevention of unexpected movements of individual mechanisms 10
5.5 Walking surfaces 11
5.6 Operation of manual controls 11
5.7 Removal of broken glass 11
5.8 Noise 11
5.9 Guards 12
5.10 Heat-protective equipment 12
5.11 Gob distributor and interceptor 12
5.12 Gob distributor operation 12
5.13 Necessary movements in case of power failure 13
5.14 Electrical equipment 13
5.15 Pneumatic system 13
5.16 Energy supply disconnecting devices 13

6 Verification of safety requirements and/or protective measures 13

7 Information for use 14
7.1 General 14
7.2 Accompanying documents (in particular: instruction handbook) 14
7.3 Marking 15

Annex A (informative) Glossary 16

Annex B (informative) Blow and blow process 17

Annex C (informative) Press and blow process 18

Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC 19

Annex ZB (informative) !Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC" 20

Bibliography 21

Tables Table 1 -- List of significant hazards 8

Table 2 -- Individual testing for requirements stated in Clause 5 13