DIN EN 13042-1:2010-04 (E)

Machines and plants for the manufacture, treatment and processing of hollow glass - Safety requirements - Part 1: Gob feeder (includes Amendment A1:2009)

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 6

4 List of significant hazards 6

5 Safety requirements and/or protective measures 8
5.1 General 8
5.2 Starting and stopping and unexpected start-up 8
5.3 Emergency-stop equipment 8
5.4 Avoiding slip hazard 8
5.5 Design of manual controls 9
5.6 Guards 9
5.7 Lockout of shears 9
5.8 Hydraulic/pneumatic system 9
5.9 Electrical equipment 9
5.10 Energy supply disconnecting devices 9
5.11 Gob-loading interruption 9
5.12 Quick release refractory chucks 10
5.13 Refractory lifting device 10
5.14 Glass flow 10
5.15 Necessary movements in case of power failure 10
5.16 Safeguarding against contact with hot surfaces 10
5.17 Noise 10

6 Verification of safety requirements and/or protective measures 11

7 Information for use 12
7.1 General 12
7.2 Accompanying documents (in particular: Instruction handbook) 12
7.3 Marking 13

Annex A (informative) Glossary 15

Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC 16

Annex ZB (informative) !!!!Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC""""" 17

Bibliography 18

Tables !!!!Table 1 -- List of significant hazards""""" 6

!!!!Table 2 -- Individual testing for requirements stated in Clause 5""""" 12