DIN EN 1822-4:2011-01 (E)

High efficiency air filters (EPA, HEPA and ULPA) - Part 4: Determining leakage of filter elements (scan method)

Contents

Page

Foreword 4

Introduction 5

1 Scope 6

2 Normative references 6

3 Terms and definitions 6

4 Description of the procedure 7

5 Test filter 8

6 Test apparatus 8
6.1 Set-up of the test apparatus 8
6.2 Test duct 11
6.2.1 Test air conditioning 11
6.2.2 Adjustment of the volume flow rate 11
6.2.3 Measurement of the volume flow rate 11
6.2.4 Aerosol mixing duct 11
6.2.5 Test filter mounting assembly 11
6.2.6 Measuring points for the pressure difference 11
6.2.7 Sampling, upstream 11
6.2.8 Screening 12
6.3 Scanning assembly 12
6.3.1 General 12
6.3.2 Sampling, downstream 12
6.3.3 Probe arm 13
6.3.4 Aerosol transport lines 13
6.3.5 Provisions to move the probe 13
6.4 Aerosol generation and measurement techniques 13
6.4.1 General 13
6.4.2 Set-up for testing with a monodisperse test aerosol 14
6.4.3 Set-up for testing with a polydisperse test aerosol 14

7 Test air 14

8 Test procedure 15
8.1 General 15
8.2 Preparatory checks 15
8.3 Starting up the aerosol generator 16
8.4 Preparing the test filter 16
8.4.1 Installing the test filter 16
8.4.2 Flushing the test filter 16
8.5 Testing 16
8.5.1 Measuring the pressure drop 16
8.5.2 Testing with monodisperse test aerosol 17
8.5.3 Testing with polydisperse test aerosol 17
8.5.4 Leak testing (local penetration) 17
8.5.5 Determining the mean efficiency of the filter element 17

9 Evaluation 18
9.1 Calculating the penetration and the efficiency 18
9.2 Local penetration 19
9.3 Mean efficiency 20
9.4 Classification 20

10 Test report 20

11 Maintenance and inspection of the test apparatus 21

Annex A (normative) Oil Thread Leak Test 23

Annex B (normative) Determining the test parameters 24

B.1 General 24
B.2 Boundary conditions 24
B.3 Test filter data 24
B.4 Data for the apparatus 25
B.4.1 Particle counters 25
B.4.2 Downstream sampling probes 25
B.4.3 Loss factor 26
B.5 Sequence of calculation steps 26
B.6 Checking the isokinetic sampling 27
B.7 Choosing the probe speed 28
B.8 Minimum aerosol concentration 29
B.9 Maximum aerosol concentration 30
B.10 Leak signal 31
B.10.1 Effective value 31
B.10.2 Signal difference 32

Annex C (informative) Example of an application with evaluation 34

Annex D (informative) Leak Test with solid PSL Aerosol 37

D.1 Background 37
D.2 General Remarks 37
D.3 Test Procedure 37
D.4 Test Protocol 39

Annex E (informative) 0,3 µm - 0,5 µm Particle Efficiency Leak Test 40

Bibliography 42