DIN EN 415-10:2014-07 (E)

Safety of packaging machines - Part 10: General requirements

Contents

Page

Foreword 5

Introduction 6

1 Scope 7

2 Normative references 7

3 Terms and definitions 10

4 List of significant hazards 11
4.1 General 11
4.2 Mechanical hazards 12
4.2.1 Moving parts 12
4.2.2 Slip, trip and fall hazards 12
4.2.3 Loss of stability 12
4.2.4 Hazards from guards 12
4.3 Pneumatic and hydraulic equipment 12
4.4 Hazards from electrical equipment 13
4.5 Hazards from electrostatic phenomena 13
4.6 Thermal hazards 13
4.6.1 Hot Surfaces 13
4.6.2 Cold surfaces 13
4.7 Noise 13
4.8 Radiation 13
4.9 Hazards from products and materials 14
4.9.1 Hazards generated by products 14
4.9.2 Hazards generated by packaging materials 14
4.10 Hazards due to neglecting ergonomic principles 15
4.11 Hazards due to neglecting hygienic design principles 15
4.12 Hazards caused by failures 15
4.12.1 General 15
4.12.2 Failure of power supplies 15
4.12.3 Failure of safety related parts of control systems 16
4.12.4 Failure of electronic drive systems 16
4.13 Hazards caused by the presence of stored energy 16
4.14 Hazards due to remote diagnostics or control 16
4.15 Reasonably foreseeable misuse 16
4.16 Hazards from specific elements or processes of packaging machines 17
4.16.1 Cutting devices 17
4.16.2 Sealing devices 17
4.16.3 Film reel unwind mechanisms 18
4.16.4 Conveyors 18
4.16.5 Handles and hand-wheels 20
4.16.6 Size or product changing 20
4.16.7 Hot melt adhesive equipment 21
4.16.8 Modified atmosphere packaging 21

5 Safety requirements and/or protective measures 21
5.1 General 21
5.2 Requirements to minimize mechanical risks 22
5.2.1 Protective measures against risks from moving parts 22

5.2.2 Requirements to prevent slip, trip and fall hazards 52
5.2.3 Stability of machines 52
5.2.4 Prevention of hazards from movable guards 53
5.3 Supply disconnecting (isolating) device 53
5.4 Pneumatic and hydraulic equipment 53
5.5 Electrical equipment 54
5.5.1 General 54
5.5.2 Protection against electric shock 54
5.5.3 Degree of protection 54
5.6 Electrostatic phenomena 54
5.7 Thermal hazards 55
5.7.1 Hot surfaces 55
5.7.2 Cold surfaces 55
5.8 Noise reduction 55
5.9 Radiation 56
5.9.1 General 56
5.9.2 Laser radiation 56
5.10 Measures to control hazards generated by products, substances and materials 57
5.10.1 Measures to control hazards generated by substances 57
5.10.2 Measures to control hazards generated by products 57
5.10.3 Measures to control hazards generated by packaging materials 59
5.11 Ergonomic design principles 60
5.11.1 Operating the machine 60
5.11.2 Operator interface and machine mounted control devices 60
5.11.3 Handling machine parts 60
5.11.4 Loading packaging materials 60
5.11.5 Loading products or unloading packages 61
5.11.6 Size or product changes 61
5.11.7 Cleaning the machine 61
5.11.8 Maintenance 61
5.11.9 Moving the machine 61
5.11.10 Lighting 62
5.12 Hygienic design requirements 62
5.13 Failures of power supplies 62
5.14 Control functions 63
5.14.1 General 63
5.14.2 Normal stop 63
5.14.3 Safety related stop functions 63
5.14.4 Operational stop 63
5.14.5 Emergency stop and emergency switching off 63
5.14.6 Safety related stops of variable speed electrical power drive systems 64
5.14.7 Stopping time 65
5.15 Failures of safety related parts of control systems 65
5.16 Prevention of unexpected start up 65
5.16.1 General 65
5.16.2 Requirements for machines where whole body access is possible 65
5.16.3 Operations with open guards 66
5.17 Stored energy 67
5.18 Requirements for remote diagnostics or control 67
5.19 Reasonably foreseeable misuse 68
5.20 Requirements for specific elements or processes of packaging machines 68
5.20.1 Cutting devices 68
5.20.2 Sealing devices 69
5.20.3 Film reel unwind mechanisms 69
5.20.4 Conveyors 69
5.20.5 Handles and hand-wheels 72
5.20.6 Size or product changing 72
5.20.7 Hot melt adhesive equipment 73
5.20.8 Modified atmosphere packaging 74

6 Verification of safety requirements and measures 74
6.1 General 74

6.2 Visual inspections with the machine stopped 75
6.2.1 Mechanical parts 75
6.2.2 Pneumatic systems 75
6.2.3 Hydraulic systems 75
6.2.4 Electrical systems 75
6.2.5 Guards 75
6.2.6 Design requirements 75
6.2.7 Marking and warning signs 75
6.3 Measurements with the machine stopped 75
6.3.1 Guards 75
6.3.2 Electrical testing 75
6.4 Visual inspections with the machine running 76
6.4.1 Guards 76
6.4.2 Safety related functions 76
6.4.3 Dissipation of stored energy 76
6.5 Measurements or tests with the machine running 76
6.5.1 Electrical testing 76
6.5.2 Measurement of noise emission 76
6.5.3 Temperature 76
6.6 Verification procedures 76

7 Information 78
7.1 General 78
7.2 Marking 78
7.3 Signals and warning signs 78
7.3.1 General 78
7.3.2 Prohibition sign "Do not reach in" 79
7.3.3 Prohibition sign "No access" 79
7.3.4 Warning sign "Hot surface" 80
7.3.5 Warning sign "Warning; Low temperature/freezing conditions" 80
7.3.6 Warning signs indicating radiation hazards 81
7.3.7 Prohibition sign "Access prohibited for persons with implantable medical devices" 83
7.4 Instructions 83
7.4.1 General 83
7.4.2 All packaging machines 84
7.4.3 Machines for use with foodstuffs or pharmaceuticals 85
7.4.4 Machines for handling hazardous products 85
7.4.5 Machines with hot or cold surfaces 85
7.4.6 Machines incorporating hot melt and other adhesive systems 85
7.4.7 Information on stability of the machine 85
7.4.8 Machines incorporating lifting equipment 86
7.4.9 Assemblies of machines 86

Annex A (informative) Evaluation of energy or force 87

Annex B (informative) Maximum values for inherently safe design 88

Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC 89

Bibliography 92