ISO 16891:2016-01 (E)

Test methods for evaluating degradation of characteristics of cleanable filter media

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols and abbreviated terms 4

5 Principle 5

6 Test specimen, equipment and test procedure 6
6.1 General 6
6.2 Preparation of sheets for gas exposure 7
6.2.1 Shape and size of tensile specimen 7
6.2.2 Sample sheet for exposure 7
6.2.3 Selection of sample sheet through air permeability measurement 8
6.2.4 Filter media for exposure 8
6.3 Sample preparation 9
6.3.1 Exposure system 9
6.3.2 Heating system 11
6.3.3 Test gas supply system 11
6.3.4 Gas analyzer 11
6.3.5 Gas treatment device 12
6.4 Exposure conditions and procedures 12
6.4.1 Exposure conditions 12
6.4.2 Exposure period and number of exposure 12
6.4.3 Attachment of filter sample sheets in the sample case 13
6.4.4 Implementation of the exposure 13

7 Tensile strength measurement of exposed specimen 14
7.1 Tensile test device 14
7.2 Preparation of a tensile test specimen 14
7.3 Method of tensile test 14
7.4 Characterization of the degradation 15

8 Test report 16

Annex A (informative) Causes and results of degradation of fabrics 17

Annex B (informative) Possible evaluation method for characteristic change of fabrics 18

Annex C (informative) Theoretical consideration of degradation mechanism 19

Annex D (informative) Determination of specimen size 22

Annex E (informative) Experimental setup for gas exposure 26

Annex F (informative) Service temperature of filter materials 30

Annex G (informative) Examples of measured data of fabric at different circumstances 31

Annex H (informative) Example of test report 37

Bibliography 41