ISO 19685:2017-09 (E)

Vacuum technology - Vacuum gauges - Specifications, calibration and measurement uncertainties for Pirani gauges

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols and abbreviated terms 4

5 Principle of Pirani gauge 4

6 Specifications for Pirani gauge 5
6.1 General 5
6.2 Measuring principle 5
6.3 Type of output 5
6.4 Range of output and output display resolution 5
6.5 Measurement range and full scale 5
6.6 Expected measurement uncertainty 5
6.7 Material exposed to gas 5
6.8 Connecting flange 5
6.9 Interface and pin-connections 6
6.10 Warm-up period 6
6.11 Compatibility between gauge tube and controller 6
6.12 Normal operating (environment) conditions 6
6.13 Electrical power supply 6
6.14 Cable length 6
6.15 Maximum bake-out temperature 6
6.16 Dimensions of gauge head and controller 6
6.17 Mounting orientation 6

7 Additional (optional) specifications for Pirani gauge 6
7.1 Long-term instability 6
7.2 Relative sensitivity factor 7
7.3 Hysteresis 7
7.4 Response time 7
7.5 Inspection record and calibration certificate 7
7.6 Configuration 7
7.7 Weight 7
7.8 Storage and transport condition 7
7.9 Photographs 7
7.10 Maximum power consumption 7
7.11 Set point of pressure 7

8 Calibration and other measurement procedures 7
8.1 General 7
8.2 Conditions for calibrations 8
8.3 Assembly and adjustments of calibration item 8
8.4 Calibration 9

8.5 Measurement uncertainties during calibration 9
8.6 Calibration certificate 9
8.7 Measurement procedure for hysteresis 10
8.8 Measurement procedure of response time 10

9 Measurement uncertainties at use 10

Annex A (informative) Typical Pirani gauge 12

Bibliography 13