DIN EN ISO 29463-4:2019-05 (Englisc h)

High-efficiency filters and filter media for removing particles in air - Part 4: Test method for determining leakage of filter elements-Scan method (ISO 29463-4:2011)

Contents

Page

European foreword 3
Foreword 4
Introduction 5
1 Scope 6
2 Normative references 6
3 Terms and definitions 7
4 Principle 7
5 Test filter 8
6 Test apparatus 8
6.1 Set-up of the test apparatus 8
6.2 Test duct 11
6.3 Scanning assembly 12
6.4 Aerosol generation and measurement techniques 13
7 Test air 14
8 Procedure 15
8.1 General 15
8.2 Preparatory checks 15
8.3 Starting up the aerosol generator 16
8.4 Preparing the test filter 16
8.5 Testing 16
9 Test report 17
10 Maintenance and inspection of the test apparatus 18
Annex A (normative) Oil thread leak test 20
Annex B (normative) Aerosol photometer filter scan test method 21
Annex C (normative) Determining the test parameters 25
Annex D (informative) Example of an application with evaluation 33
Annex E (informative) Leak test with solid PSL aerosol 36
Annex F (informative) 0,3 µm to 0,5 µm particle efficiency leak test 39
Annex G (informative) Calculation of aerosol challenge 41
Bibliography 43