DIN EN 1822-4:2001-02 (E)

High efficiency particulate air filters (HEPA and ULPA) - Part 4: Determining leakage of filter elements (Scan method); English version of DIN EN 1822-4

Contents

Page

Foreword 3

Introduction 3

1 Scope 4

2 Normative references 4

3 Terms and definitions 4
3.1 sampling volume flow rate 4
3.2 sampling duration 5
3.3 total particle count method 5
3.4 particle counting and sizing method 5
3.5 particle flow rate 5
3.6 particle flow distribution 5

4 Description of the procedure 5

5 Test filter 6

6 Test apparatus 7
6.1 Set-up of the test apparatus 7
6.2 Test duct 9
6.3 Scanning assembly 10
6.4 Aerosol generation and measurement techniques 11

7 Test air 13

8 Test procedure 13
8.1 General 13
8.2 Preparatory checks 14
8.3 Starting up the aerosol generator 14
8.4 Preparing the test filter 15
8.5 Testing 15

9 Evaluation 17
9.1 Calculating the penetration and the efficiency 17
9.2 Local penetration 19
9.3 Mean efficiency 19
9.4 Classification 19

10 Test report 19
10.1 Details of the test filter 19
10.2 General details of the test parameters 19
10.3 Test results 20

11 Maintenance and inspection of the test apparatus 20

Annex A (normative) Oil thread test 22

Annex B (normative) Determining the test parameters 23

Annex C (informative) Example of an application with evaluation 33

Bibliography 35