DIN EN ISO 19085-6:2025-04 (E)

Woodworking machines - Safety - Part 6: Single spindle vertical moulding machines (toupie) (ISO 19085-6:2024)

Contents

Page

European foreword ... **5**

Annex ZA (informative) **Relationship between this European Standard and the essential requirements of Directive 2006/42/EC aimed to be covered** ... **6**

Foreword ... **9**

Introduction ... **10**

1 Scope ... **12**

2 Normative references ... **13**

3 Terms and definitions ... **13**

4 Safety requirements and measures for controls ... **20**
4.1 Safety and reliability of control systems ... 20
4.2 Control devices ... 20
4.3 Start ... 21
4.3.1 Direct start ... 21
4.3.2 Start via control power-on ... 21
4.4 Safe stops ... 22
4.4.1 General ... 22
4.4.2 Normal stop ... 22
4.4.3 Operational stop ... 22
4.4.4 Emergency stop ... 22
4.5 Braking function of tools ... 22
4.6 Mode selection ... 22
4.7 Tool speed changing ... 22
4.7.1 Speed changing by shifting the belts on the pulleys ... 22
4.7.2 Speed changing by incremental speed change motor ... 22
4.7.3 Infinitely variable speed by frequency inverter ... 22
4.7.4 Speed limiting device for tenoning ... 22
4.7.5 Changing the direction of tool rotation ... 23
4.8 Failure of any power supply ... 23
4.9 Manual reset control ... 24
4.10 Standstill detection and monitoring ... 24
4.11 Machine moving parts speed monitoring ... 24
4.12 Time delay ... 24
4.13 Teleservice ... 24
4.14 Power-driven adjustment of arbor, demountable power feed unit, fences and table insert ... 24

5 Safety requirements and measures for protection against mechanical hazards ... **25**
5.1 Stability ... 25
5.2 Risk of break-up during operation ... 25
5.3 Tool and tool fixing design ... 25
5.3.1 General ... 25
5.3.2 Spindle locking ... 28
5.3.3 Circular saw blade fixing device ... 28
5.3.4 Flange dimension for circular saw blades ... 28
5.3.5 Arbor rings ... 28
5.3.6 Quick tool/arbor change system ... 28
5.3.7 Manual adjustment of arbor height ... 29
5.3.8 Manual adjustment of arbor inclination ... 29
5.4 Braking ... 30
5.4.1 Braking of tools ... 30

5.4.2 Maximum run-down time 30
5.4.3 Brake release 30
5.5 Safeguards 30
5.5.1 Fixed guards 30
5.5.2 Interlocking movable guards 30
5.5.3 Hold-to-run control 30
5.5.4 Two-hand control 30
5.5.5 Electro-sensitive protective equipment (ESPE) 30
5.5.6 Pressure-sensitive protective equipment (PSPE) 30
5.5.7 Enabling control 31
5.6 Prevention of access to hazardous moving parts 31
5.6.1 Access to the tool below the table 31
5.6.2 Safeguarding for straight work 31
5.6.3 Safeguarding for curved work 33
5.6.4 Safeguarding for tenoning 34
5.6.5 Safeguarding the glass bead saw blade 35
5.6.6 Guarding of drives 35
5.7 Impact hazard 35
5.8 Clamping devices 35
5.9 Measures against ejection 35
5.9.1 General 35
5.9.2 Guards materials and characteristics 35
5.9.3 Anti-kickback devices 36
5.10 Workpiece supports and guides 38
5.10.1 Machine table 38
5.10.2 Workpiece guiding for straight work 41
5.10.3 Workpiece guiding for curved work 42
5.11 Safety appliances 43

6 Safety requirements and measures for protection against other hazards 43
6.1 Fire 43
6.2 Noise 43
6.2.1 Noise reduction at the design stage 43
6.2.2 Noise emission measurement and declaration 44
6.3 Emission of chips and dust 44
6.4 Electricity 44
6.5 Ergonomics and handling 44
6.6 Lighting 44
6.7 Pneumatics 44
6.8 Hydraulics 45
6.9 Electromagnetic compatibility 45
6.10 Laser 45
6.11 Static electricity 45
6.12 Errors of fitting 45
6.13 Isolation 45
6.14 Maintenance 45
6.15 Relevant but not significant hazards 45

7 Information for use 45
7.1 Warning devices 45
7.2 Marking 45
7.2.1 General 45
7.2.2 Additional markings 45
7.3 Instruction handbook 46
7.3.1 General 46
7.3.2 Additional information 46

Annex A (informative) **List of significant hazards 49**

Annex B (informative) **Performance level required 51**

Annex C (normative) **Stability test 52**

Annex D (normative) **Test for braking function 53**

Annex E (normative) **Impact test for guards 54**

Annex F (normative) **Noise test code** **55**
Annex G (informative) **Determination of maximum spindle speeds for single piece arbors** **58**
Annex H (normative) **Rigidity test for pressure pads, hand protectors and guiding steadies** **62**
Bibliography **68**