ISO/PAS 5672:2023-11 (E)

Robotics - Collaborative applications - Test methods for measuring forces and pressures in human-robot contacts

Contents

Page

Foreword ... **iv**

Introduction ... **v**

1 Scope ... **1**

2 Normative references ... **1**

3 Terms and definitions ... **1**

4 Overview ... **2**
4.1 General ... 2
4.2 Contact types ... 2
4.3 Contact locations ... 4

5 Measuring instrument ... **4**
5.1 General ... 4
5.2 Design parameters ... 5
5.3 Calibration ... 6
5.4 Sensor characteristics ... 7
5.4.1 General ... 7
5.4.2 Force sensors ... 8
5.4.3 Pressure sensors ... 8

6 Measurement methods ... **8**
6.1 General ... 8
6.2 Pinch and crush ... 10
6.2.1 General ... 10
6.2.2 Limited space for PFMD installation ... 10
6.3 Impact ... 11
6.3.1 General ... 11
6.3.2 PFMD with a moveable measuring unit ... 11
6.3.3 Fixed PFMD and conversion technique ... 12
6.4 PFMD position ... 13

7 Measurement procedure ... **14**
7.1 General ... 14
7.2 Test preparation ... 15
7.2.1 General ... 15
7.2.2 Contact area lies on the robot ... 15
7.2.3 Contact area lies in the environment ... 15
7.3 Test execution ... 15
7.4 Analysis ... 15
7.5 Test report ... 17

Annex A (informative) **Rigid support structures for PFMD installation** ... **19**

Annex B (informative) **Reduction of pressure image resolution** ... **22**

Annex C (informative) **Example 1: Pick-and-place application** ... **24**

Annex D (informative) **Example 2: Mobile picker** ... **33**

Annex E (informative) **Reporting templates** ... **38**

Bibliography ... **41**