ISO 20553:2006-04 (E)

Radiation protection - Monitoring of workers occupationally exposed to a risk of internal contamination with radioactive material

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 2

3 Terms and definitions 2
3.1 Absorption types 2

4 Symbols and abbreviated terms 6

5 Purpose and need for monitoring programmes 6

6 Reference levels 8

7 Routine monitoring programmes 9
7.1 General aspects 9
7.2 Workplace monitoring 10
7.3 Individual monitoring 10
7.4 Methods and time intervals 11

8 Special monitoring programmes 14
8.1 General aspects 14
8.2 Workplace monitoring 14
8.3 Individual monitoring 15

9 Task-related monitoring programmes 17
9.1 General aspects 17
9.2 Workplace monitoring 17
9.3 Individual monitoring 17

10 Special cases of individual monitoring 18
10.1 Actinides 18
10.2 Contamination in wounds 18
10.3 Contamination on the skin 18

11 Recording, documentation and reporting 18
11.1 Recording and documentation 18
11.2 Reporting 20

12 Quality management 20

Bibliography 22