# ISO 15011-2:2009-10 (E)

## Health and safety in welding and allied processes - Laboratory method for sampling fume and gases - Part 2: Determination of the emission rates of carbon monoxide (CO), carbon dioxide (CO<(Index)2>), nitrogen monoxide (NO) and nitrogen dioxid e (NO<(Index)2>) during arc welding, cutting and gouging

## Contents

Page


Foreword ..... iv

Introduction ..... v

1 Scope ..... 1

2 Normative references ..... 1

3 Terms and definitions ..... 1

4 Principle ..... 2

5 Equipment and materials ..... 2

6 Test procedures ..... 4
6.1 Welding procedure selection ..... 4
6.2 Setting up the test equipment ..... 4
6.3 Blank test ..... 5
6.4 Manual metal arc welding ..... 5
6.5 Continuous wire processes and autogeneous TIG welding ..... 5
6.6 Cutting and gouging ..... 6

7 Calculating and reporting the results ..... 7

Annex A (informative) Possible designs of hood ..... 8

Annex B (informative) Equipment notes ..... 10

Annex C (informative) Welding parameters for gas-shielded arc welding ..... 12

Annex D (normative) Test procedures ..... 15

Annex E (normative) Calculation of the average stable gas concentration ..... 16

Annex F (normative) Test report ..... 17

Bibliography ..... 18