DIN EN 13100-4:2013-01 (E)

Non destructive testing of welded joints of thermoplastics semifinished products - Part 4: High voltage testing

Contents

Page

Foreword 3

1 Scope 4

2 Terms and definitions 4

3 Symbols and designations 4

4 Principle of the test 4

5 Equipment types 5
5.1 General 5
5.2 High frequency spark tester 5
5.3 DC Holiday detector 5
5.4 Pulsed Holiday detector 6

6 Determination of test voltage 6
6.1 General 6
6.2 Butt joints 6
6.3 Overlap joints 7

7 Test electrode 8

8 Test procedure 8
8.1 DC and pulsed holiday detectors 8
8.2 High frequency spark testers 9

9 Test report 9