DIN EN 13100-2:2019-11 (E)

Non-destructive testing of welded joints in thermoplastics semi-finished products - Part 2: X-ray radio graphic testing

Contents

Page

European foreword 3

1 Scope 4

2 Normative references 4

3 Terms and definitions 4

4 Symbols and abbreviations 5

5 General 6
5.1 Security measures 6
5.2 Surface preparation and stage of manufacture 6
5.3 Location of the weld in the radiograph 6
5.4 Identification of radiographs 6
5.5 Marking 7
5.6 Overlap of films 7
5.7 Types and position of image quality indicators (IQI) 7
5.8 Evaluation of image quality 7
5.9 Minimum image quality values 8
5.10 Personnel qualification 8

6 Recommended techniques for making radiographs 8
6.1 Test arrangements 8
6.2 Choice of tube voltage 11
6.3 Film systems and screens 11
6.4 Alignment of beam 11
6.5 Source-to-object distance 12
6.6 Maximum area for a single exposure 12
6.7 Density of radiograph 12
6.8 Processing 12
6.9 Film viewing conditions 13

7 Examination report 13

Annex A (normative) Minimum image quality values 15

Annex B (informative) Recommended number of exposures when using the perpendicular, double-wall, single-image and single-wall off-centre techniques for a circumferential butt weld ... 18

Bibliography 20