# ISO 15616-3:2003-03 (E)

## Acceptance tests for CO<(Index)2>-laser beam machines for high quality welding and cutting - P art 3: Calibration of instruments for measurement of gas flow and pressure

## Contents

Page

page Foreword .....v

1 Scope .....1

2 Normative references .....1

3 Purpose of the measurements .....1

4 Gas pressure and gas flow .....1

5 Examination procedure .....1
5.1 General .....1
5.2 Measuring devices and procedure .....1