ISO 17846:2004-05 (E)

Welding and allied processes - Health and safety - Wordless precautionary labels for equipment and consum ables used in arc welding and cutting

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Requirements for wordless precautionary labels 2
4.1 Use of precautionary labels on products 2
4.2 Label elements 2
4.3 Design of precautionary labels 2
4.4 Use of symbols 2
4.5 Uniformity of symbols 2
4.6 Label legibility, placement, visibility, and durability 3
4.7 The basic precautionary label 3
4.8 The wordless label for plasma arc cutting equipment 3
4.9 The precautionary label for engine-driven welding and cutting equipment 3
4.10 The precautionary label for wire feeding equipment 3
4.11 Precautionary labels for other hazards 3

Annex A (informative) Precautionary label symbols 4

Annex B (informative) Examples of wordless precautionary labels 10

Bibliography 18