ISO 15614-10:2005-02 (E)

Specification and qualification of welding procedures for metallic materials - Welding procedure test - Part 10: Hyperb aric dry welding

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Preliminary welding procedure specification (pWPS) 2

5 Welding procedure test 3

6 Test piece 3
6.1 General 3
6.2 Shape and dimensions of test pieces 3
6.3 Welding of test pieces 3

7 Examination and testing 4
7.1 Extent of testing 4
7.2 Location and cutting of test specimens 4
7.3 Non-destructive testing 4
7.4 Destructive tests 4
7.5 Re-testing 4

8 Range of qualification 4
8.1 General 4
8.2 Related to the manufacturer 5
8.3 Related to the parent material 5
8.4 Common to all welding procedures 5
8.5 Specific to processes 7
8.6 Specific to hyperbaric environment 7

9 Welding procedure qualification record (WPQR) 8