DIN EN 482:2012-06 (E)

Workplace exposure - General requirements for the performance of procedures for the measurement of chemical agents

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 6

4 Classification 6
4.1 General 6
4.2 Screening measurements of time weighted average concentration 6
4.3 Screening measurements of variation of concentration in time and/or space 6
4.4 Measurements for comparison with (occupational exposure) limit values and periodic measurements 6

5 Performance requirements 6
5.1 General 6
5.2 Screening measurements of time weighted average concentration 7
5.3 Screening measurements of variation of concentration in time and/or space 7
5.4 Measurements for comparison with limit values and periodic measurements 7
5.4.1 Unambiguity 7
5.4.2 Selectivity 7
5.4.3 Averaging time 7
5.4.4 Measuring range 7
5.4.5 Expanded uncertainty 8
5.5 Composite procedures 8
5.6 Transport and storage 8
5.7 Environmental conditions 8
5.8 Description of measuring procedure 9
5.9 Dimension of result 9
5.10 Additional requirements 9

6 Test method 9

7 Validation report 10

Annex A (informative) Structure of a method description 11

Annex B (informative) Calculation of uncertainty of measurement 12

B.1 General 12
B.2 Uncertainty associated with sampled air volume or mass uptake 13
B.3 Uncertainty associated with sampling efficiency 15
B.4 Uncertainty associated with sample storage and transportation 17
B.5 Uncertainty associated with method recovery for gases and vapours 17
B.6 Uncertainty associated with analytical recovery for airborne particles and mixtures of airborne particles and vapour 17
B.7 Uncertainty associated with method variability for gases and vapours 18

B.8 Uncertainty associated with analytical variability for airborne particles and mixtures of airborne particles and vapour 18
B.9 General equation for combination of uncertainty components 18

Bibliography 20